US ERA ARCHIVE DOCUMENT

		Ļ
_		ĺ
_		
ш		
≥		
_		
_		l
ັບ		
$\equiv$		
O		L
۵		
ш		
>		
I		
5		
$\sim$		
œ		
◂		
4		
◂		
$\mathbf{a}$		
Ш		
S		
_		
	ľ	

1. Incident Name		2. Date Pr	repared	3. Time Prepared	UNIT LOG		
Kalamazoo River/Enb	oridge Spill	05/24/2012 1330		1330	ICS 214		
4. Unit Name/Design	<u>nators</u>	5. Unit Leader		6. Operational Period :			
Operations Unit/Containment Branch Monitoring Group		Name:	Dan Capone & Joe Victory (START/US EPA)		From:	05/24/2012 0615	
		Position: Operations Section Chief		То:	05/24/2012 1230		
	7. Personnel Roster Assigned						
	Name	ICS Position		DUTY CELL			
Dan Capone		Operations Section Chief					
Joe Victory		Operations Section Chief					
Rex Johnson		Deputy Director					
Dan Zahner		Field Team Lead					
Greg Wagner	Greg Wagner		CBM Team 2				
		8. A	ctivity Lo	9			
					LAT	LAT	
Activity Area					Various	Various	
					(DD.MMMM)	(DD.MMMM)	
OIL OBSERVED	EXTENT OF OIL IMPACE DENSITY OF OIL /SHEE		<u> </u>				
Total Collection Points							
Total Boom							

# Weston/START Containment Branch Monitoring Group (CBM) Team Activity:

Greg Wagner and Dylan Massey conducted (1) Control & Containment Point inspections at shoreline and overbank locations from Kalamazoo River mile post 18.75 (D2) through Morrow Lake. (2) Water & Sediment Temperature & Level Readings. (3) Performed buoy inspections.

- 0630: Meeting with EPA, START, and Enbridge contractors to discuss Containment Operations.
- 0730- 1230: START and LBG members conducted inspections. Observations and recommended actions were logged in the START CBM Team 2 log book, as well as discussed with Dylan Massey. Dylan Massey informed Enbridge contractors to make recommended actions.

## WATER/SEDIMENT TEMPERATURE AND LEVEL READINGS:

#### Activity

**Deployed** 

LOCATION	WATER TEMP	SEDIMENT TEMP	WATER LEVEL
MP 2.25 (C 0.0 Launch)			
MP 5.25 (C0.4 Launch)			
MP 10.0 (C3.2 Launch)			
MP 15.0 (C5 Launch)			
MP 18.75 (D2 Launch)	69.0	63.2	1.0
MP 21.5 (D5)	67.5	64.6	4.5
MP 27.0 (E0.5 Launch)	68.9	67.2	0.7
MP 30.0 (E2 Launch)	67.8	66.4	0.8
MP 35.0 (E3 Launch)	65.5	60.8	0.0
MP 38.0 (E4 Launch)	66.0	66.5	0.6
AVERAGE	67.45	64.78	1.27

### **WEEKLY/AFTER RAIN EVENT INSPECTION:**

**Talmadge Creek:** (11) Pom-Poms deployed at 7 culvert locations:

MP 0.00: Upstream of source:

MP 0.04: Below Source (Culvert 1):

MP 0.27: Between Source & Division Road (Culvert 2):

MP 0.50: Division Road (Culvert 3): MP 0.74: Hillbilly Road (Culvert 4):

MP 1.09: 16 Mile Road (Culvert 5):

MP 1.28: 15 1/2-Mile Road (Culvert 6): MP 1.57: B4.5 (Culvert 7):

MP 1.77: Saylor's Property (Culvert 8): MP 1.99: A Drive North (Culvert 9):

MP 2.02: Talmadge Creek before Confluence:

#### **DAILY CONTAINMENT MONITORING:**

**<u>Kalamazoo River:</u>** Control (CT) & Containment (CTM) Points (14) deployed are:

MP 5.75 (Ceresco Dam):

MP 8.50 L1 (8.48 LDB):

MP 8.50 L3 (8.48 LDB):

MP 8.75 R1:

MP 9.00 I2 (8.97I):

MP 10.75 LDB:

MP 11.75 L2 (11.79 LDB):

MP 14.98I:

MP 15.65 (Battle Creek Spillway): Control point boom intact. No sheen observed today.

MP 17.00 L1 (Rock Tenn): Containment has been removed.

MP 21.50 (Oxbow): Silver sheen observed inside the containment. Area of sheen is 1' x 15' = 15 sq. ft.

MP 30.8 LDB: Containment site not visited today.

MP 37.75 (E4): Observed silver sheen at the control point collection point today. Area of sheen is 1' x 600' =

600 sq. ft.

### **RIVER REOPENING MILE POSTS:**

MP -2.70 to MP 2.25:

MP 2.25 to MP 5.90:

MP 5.90 to MP 9.50:

MP 9.50 to MP 13.75:

MP 13.75 to MP 15.65:

MP 15.65 to MP 18.75: MP 18.75 to MP 30.00:

MD 20.00 - MD 27.27

MP 30.00 to MP 35.25

MP 35.25 to MP 37.75:

MP 37.75 to MP 40.00:

Total sheen in control points: 600 sq. ft. Total sheen within containment: 15 sq. ft.

Total Sheen: 615 sq. ft.

## **Helicopter Fly-Over Pictures:**

No inspections resulting from overflight pictures were performed today.

Health and Safety

None

Issues	
Comments	None.